

- 1 Ferrule
- 2 Perfect circle
- 3 Wire
- 4 Electric insulator
- 5 Electroformed portion
- 6 Drawing jig
- 7 Groove
- 8 Electroforming liquid
- 9 Positive electrode
- 10 Supporting jig
- 11 Air stirring nozzle
- 12 Spring
- 13 Negative electrode
- 14 Upper plate
- 15 Lower plate
- 16 Supporting column
- 17 Stainless steel screw
- 18 Clip
- 19 Circular hole
- 20 Hook portion

FIG. 1(a)




FIG. 1(b)




FIG. 2




FIG. 3




FIG. 4




FIG. 5(a)




FIG. 5(b)






FIG. 7





FIG. 8(a)



FIG. 8(b)




FIG. 8(c)




FIG. 8(d)




FIG. 8(e)




FIG. 8(f)




FIG. 8(g)

